

x64 bit VM VMotion Issues between HP DL 385G1 to HP DL 585 G2

Hi, Solution for X64bit VM VMotion issues between HP DL 385G1 to HP DL 585 G2 is attached as text file, I am not able to find the solution in internet and I found the fix to resolve it, so I am adding this document for help others, please refer the attached txt file contains configuration which need to be added in VPXD.CFG.

Thanks

Vijay